


<b>A</b>		<b>5</b> PCS
<b>B</b>		<b>1</b> PCS
<b>C</b>		<b>1</b> PCS
<b>D</b>		<b>1</b> PCS
<b>E</b>		<b>1</b> PCS
<b>F</b>		<b>2</b> PCS
<b>G</b>		<b>1</b> PCS
<b>H</b>		<b>1</b> PCS
<b>I</b>	 6x20mm	<b>4</b> PCS
<b>J</b>	 6x35mm	<b>10</b> PCS
<b>L</b>	 4x25mm	<b>2</b> PCS
<b>M</b>		<b>10</b> PCS
<b>N</b>	 M5	<b>1</b> PCS

